

Release Notes

Belimo Energy Valve™ Software Version 3.2.1

Date: March 6th, 2020

This firmware update solves an issue, which was found on test devices only and which might occur due too much data in the memory.

The result is that the Energy Valve no longer reacts and a restart must be initiated.

This update is only effective for actuators with new OC module from production date 13.3.2019